

Water Testing Results - Sweetbriar Elementary

Action Level is 15 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result
Kitchen, southeast	21820700-001KF23A	6/16/2023	2.46
Kitchen, north	21820700-002KF23A	6/16/2023	5.4
Kitchen, north	21820700-003KF23A	6/16/2023	6.85
Kitchen center island	21820700-004KF23A	6/16/2023	8.8
Kitchen southeast	21820700-005SF23A	6/16/2023	3.35
Gym teacher restroom	21820700-006SF23A	6/16/2023	20.7
Gym	21820700-007WB23A	6/16/2023	ND
Gym	21820700-008DW23A	6/16/2023	ND
SW corridor	21820700-009DW23A	6/16/2023	ND
SW corridor	21820700-010DW23A	6/16/2023	ND
SW corridor	21820700-011WB23A	6/16/2023	ND
SW corridor boy's restroom	21820700-012BF23A	6/16/2023	5.55
SW corridor boy's restroom	21820700-013BF23A	6/16/2023	3.7
SW corridor girl's restroom	21820700-014BF23A	6/16/2023	14.8
SW corridor girl's restroom	21820700-015BF23A	6/16/2023	4.28
Room 22	21820700-016CF23A	6/16/2023	24
Nurses station bathroom	21820700-017NS23A	6/16/2023	0.581
Main office staff restroom	21820700-018SF23A	6/16/2023	1.91
Main office kitchen	21820700-019SF23A	6/16/2023	1.56
Main office kitchen	21820700-020WB23A	6/16/2023	ND
South classroom cluster west bathroom	21820700-021BF23A	6/16/2023	1.21
Room 1	21820700-022DW23A	6/16/2023	0.725
Room 1	21820700-023CF23A	6/16/2023	13.5
Room 2	21820700-024CF23A	6/16/2023	11.1
Room 2	21820700-025DW23A	6/16/2023	0.443
Outside Room 3	21820700-026DW23A	6/16/2023	ND
Outside Room 3	21820700-027CF23A	6/16/2023	16.1
Outside Room 4	21820700-028DW23A	6/16/2023	0.41

Outside Room 4	21820700-029CF23A	6/16/2023	18
Room 5	21820700-030DW23A	6/16/2023	0.374
Room 5	21820700-031CF23A	6/16/2023	31.9
South classroom cluster east bathroom	21820700-032BF23A	6/16/2023	3.87
SE classroom cluster, west	21820700-033CF23A	6/16/2023	5.21
SE classroom cluster, west	21820700-034DW23A	6/16/2023	ND
SE classroom cluster, east	21820700-035CF23A	6/16/2023	0.593
SE classroom cluster, east	21820700-036DW23A	6/16/2023	ND
NE classroom cluster, east	21820700-037CF23A	6/16/2023	5.51
NE classroom cluster, west	21820700-038CF23A	6/16/2023	3.94
NE classroom cluster, west	21820700-039DW23A	6/16/2023	ND
North classroom cluster, east bathroom	21820700-040BF23A	6/16/2023	0.71
Room 15	21820700-041DW23A	6/16/2023	0.311
Room 15	21820700-042CF23A	6/16/2023	14
Room 16	21820700-043CF23A	6/16/2023	2.1
Room 16	21820700-044DW23A	6/16/2023	ND
Outside Room 17	21820700-045DW23A	6/16/2023	0.394
Outside Room 17	21820700-046CF23A	6/16/2023	3.11
Outside Room 18	21820700-047DW23A	6/16/2023	ND
Outside Room 18	21820700-048CF23A	6/16/2023	5.38
Room 19	21820700-049DW23A	6/16/2023	12.8
Room 19	21820700-050CF23A	6/16/2023	24
North classroom cluster, west	21820700-051BF23A	6/16/2023	1.91
Counselor	21820700-052CF23A	6/16/2023	22.7
Room 23	21820700-053CF23A	6/16/2023	2.9
Room 24	21820700-054CF23A	6/16/2023	17.9
Second floor teachers lounge	21820700-055WB23A	6/16/2023	ND
Second floor teachers lounge	21820700-056SF23A	6/16/2023	1.75
Second floor teachers lounge west bathroom	21820700-057SF23A	6/16/2023	4.33
Second floor teachers lounge east bathroom	21820700-058SF23A	6/16/2023	5.5
Any fixture testing at or above the action level of 15 ppb is immediately removed from service and cannot be returned to service until it has been remediated and passed follow-up testing			
RETESTS			

ND = Non Detect - Lead level is below the set detection limits of 0.2 ppb			