




Fairview Elementary
Aerial Construction Photos
May 2017 – March 2018




Fairview Elementary
Aerial View - South
May 2017

An aerial photograph showing a large construction site for Fairview Elementary. The site is a cleared, brown dirt area enclosed by orange safety fencing. Several pieces of heavy machinery, including excavators and a bulldozer, are visible within the site. To the northwest of the construction site is a large, multi-story brick building with a flat roof. To the northeast is a large, white, L-shaped industrial building. A multi-lane highway with several cars and trucks is visible in the upper right. Residential houses and trees are scattered around the perimeter of the construction site. A white text box with a black border is overlaid in the bottom left corner.

Fairview Elementary
Aerial View - Northwest
June 2017

An aerial photograph showing the construction site for Fairview Elementary. The site is a large, rectangular area of cleared land, mostly brown dirt, with some concrete foundations and rebar visible. An orange excavator is working in the lower center of the site. To the left of the site is a large, two-story brick building with a flat roof. To the right is a parking lot with several cars and a row of white portable toilets. In the background, there is a multi-lane highway with traffic, a grassy area with a small pond, and more trees. The foreground shows a street intersection and some smaller commercial buildings.


Fairview Elementary
Aerial View - Northwest
July 2017

An aerial photograph showing the construction site for Fairview Elementary. The site is a large, cleared area of brown earth, enclosed by an orange safety fence. Inside the site, there are several excavators, including a prominent yellow one in the foreground, and various construction materials like stacks of lumber and concrete blocks. To the north of the site is a large, modern-looking building with a blue and white facade. To the east, there's a parking lot filled with cars and a few small white buildings. A multi-lane highway with several buses is visible in the upper right. The surrounding area includes green trees and some residential houses.


Fairview Elementary
Aerial View - Northwest
August 2017




Fairview Elementary
Aerial View - West
September 2017

An aerial photograph showing the construction of a new building at Fairview Elementary. The central focus is a large, rectangular structure with its wooden frame exposed, showing multiple bays. To its right, a smaller, partially completed concrete structure is visible. A yellow crane stands near the main building. The site is surrounded by various construction materials, including stacks of lumber and concrete blocks. In the background, there are existing school buildings, one with a blue facade and another with a red facade. The foreground and sides of the site are lined with trees, some of which have autumn-colored foliage. A parking lot with several cars is located to the right of the construction area. The overall scene depicts an active construction project in a school setting.


Fairview Elementary
Aerial View - Southwest
October 2017

An aerial photograph showing the construction of a new building at Fairview Elementary. The site is located between an existing brick school building on the left and a parking lot with several white portable offices on the right. The new building's foundation and lower walls are visible, with some sections covered in orange safety fencing. A large pile of dirt and construction materials is in the foreground, with an excavator and other heavy machinery nearby. A blue tarp-covered pile of debris is visible in the background. The scene is captured from a high angle, showing the layout of the construction area and surrounding infrastructure.


Fairview Elementary
Aerial View - Northwest
November 2017

An aerial photograph showing the construction of a new building at Fairview Elementary. The site is located between an existing brick school building and a multi-lane highway. The new building's foundation and lower walls are visible, with some sections featuring blue and yellow insulation or formwork. Construction equipment, including excavators and trucks, is active on the site. A large pile of materials is covered with a blue tarp. The surrounding area includes a parking lot, some trees, and a residential neighborhood with a house and a swimming pool visible in the lower right.


Fairview Elementary
Aerial View - Northwest
December 2017

An aerial photograph showing the construction of Fairview Elementary school. The main building is a large, multi-winged structure with a dark roof and blue and orange exterior panels. A large section of the roof is covered in blue insulation. To the left is an older brick building. The site is surrounded by parking lots with cars and trucks, and a road with a grassy median runs along the top. A white text box in the bottom left corner contains the following text:


Fairview Elementary
Aerial View - Northwest
January 2018

An aerial photograph of Fairview Elementary school during its construction phase in February 2018. The school building is a large, multi-winged structure with a complex roofline. The roof is primarily white, with several sections of blue insulation or temporary roofing visible. The exterior walls are a mix of brick and light-colored panels. The building is surrounded by a large parking lot filled with cars and trucks. To the left of the main building is a large, blue-roofed industrial or warehouse building. To the right is a smaller, tan-colored building. The surrounding area is covered in snow, indicating a winter setting. Various construction vehicles, including excavators, trucks, and cranes, are visible around the site. The overall scene depicts a busy construction project in a suburban or urban environment.


Fairview Elementary
Aerial View - Northwest
February 2018

An aerial photograph of Fairview Elementary school during a major renovation project in March 2018. The main building is a large, multi-winged structure with a flat roof. Significant portions of the exterior walls are covered in blue insulation or sheathing, while other sections show brickwork and wooden siding. The roof is cluttered with construction materials, including stacks of lumber, pipes, and various pieces of equipment like cranes and lifts. To the left of the main building is a smaller, older brick structure. In the background, there's a large white industrial-style building with a blue roofline. The school is surrounded by a parking lot filled with cars and several portable trailers. A flagpole with the American flag stands near the white building. In the foreground, a street with some parked cars and trees is visible. The overall scene depicts an active and extensive construction project.

Fairview Elementary
Aerial View - Northwest
March 2018

An aerial photograph of Fairview Elementary school during a major renovation project in April 2018. The main building is a large, multi-story structure with a flat roof. A significant portion of the roof and the exterior walls of several wings are covered in blue insulation or sheathing, indicating ongoing construction. The building is surrounded by a parking lot filled with cars and several portable trailers. In the foreground, there is a large area of construction materials, including stacks of lumber, concrete blocks, and debris. A yellow crane and other construction equipment are visible on the site. To the left, there is a smaller brick building and a playground area. In the background, there are more industrial-style buildings and a grassy field.

Fairview Elementary
Aerial View - Northwest
April 2018

An aerial photograph of Fairview Elementary school during a major renovation or construction project in May 2018. The main building is a large, multi-story structure with a complex roofline. Significant portions of the exterior walls and roof are covered in blue insulation or sheathing, indicating ongoing construction. The roof is cluttered with construction materials, including stacks of white panels, pipes, and various tools. Several construction vehicles, including excavators, trucks, and a yellow crane, are positioned around the building. To the left of the main building is a large, older brick building with a flat roof. To the right is a large parking lot filled with numerous cars and several white delivery vans. In the background, a multi-lane highway runs horizontally across the top of the frame, with a grassy area and trees between the road and the school grounds. The overall scene depicts a busy construction site in a suburban or urban setting.

Fairview Elementary
Aerial View - Northwest
May 2018