




Fairview Elementary
Aerial Construction Photos
May 2017 – October 2017




Fairview Elementary
Aerial View - South
May 2017

An aerial photograph showing a large construction site for Fairview Elementary. The site is a cleared, brown dirt area enclosed by orange safety fencing. Several pieces of heavy machinery, including excavators and a bulldozer, are visible within the site. To the left of the construction area is a large, multi-story building with a grey roof and blue and red brickwork. To the right is a large, empty parking lot with a few vehicles and a white trailer. In the background, a multi-lane highway with several cars and trucks is visible, along with a line of trees. The foreground shows residential houses and a street intersection.

Fairview Elementary
Aerial View - Northwest
June 2017

An aerial photograph showing the construction site for Fairview Elementary. The site is a large, rectangular area of cleared land, mostly brown dirt, with some concrete foundations and rebar visible. An orange excavator is working in the lower center of the site. To the left of the site is a large, two-story brick building with a flat roof. To the right is a parking lot with several cars and a row of white portable toilets. In the background, there is a multi-lane highway with traffic, and further back, a residential area with houses and trees. A small pond is visible in the upper left. The entire scene is captured from a high angle, providing a clear view of the construction progress and surrounding environment.


Fairview Elementary
Aerial View - Northwest
July 2017

An aerial photograph showing the construction site for Fairview Elementary. The site is a large, cleared area of brown earth, enclosed by an orange safety fence. Inside the site, there are several excavators, including a prominent yellow one in the foreground, and various construction materials like lumber and concrete blocks. To the north of the site is a large, modern-looking building with a blue and white facade. To the east, there's a parking lot filled with cars and a few small white buildings. A multi-lane highway with several buses is visible in the upper right. The surrounding area includes trees, other buildings, and a small pond in the distance.

Fairview Elementary
Aerial View - Northwest
August 2017



Fairview Elementary
Aerial View - West
September 2017

An aerial photograph showing the construction of a new building at Fairview Elementary. The central focus is a large structure with its wooden frame exposed, featuring a grid of beams. To its right, a smaller, partially completed concrete building stands. A yellow crane is positioned near the wooden frame. The site is surrounded by various construction materials, including stacks of lumber and orange safety barriers. In the background, there are existing school buildings, one with a blue facade and another with a red facade. The foreground is filled with trees displaying autumn foliage in shades of green, yellow, and red. A parking lot with several cars is visible on the right side of the construction area.

Fairview Elementary
Aerial View - Southwest
October 2017



Fairview Elementary
Zoomed Aerial view - South
October 2017
