


An aerial photograph showing the construction of Fairview Elementary. The site is located between a multi-lane highway on the left and a residential neighborhood on the right. A long line of blue and white semi-trailers is parked along the highway. The construction area includes several buildings under construction, some with orange roofs, and a large white warehouse-like building. The surrounding area is filled with trees showing autumn foliage and houses.


Fairview Elementary
Aerial Construction Photos
May 2017 – March 2018




Fairview Elementary
Aerial View - South
May 2017

An aerial photograph showing a large construction site for Fairview Elementary. The site is a rectangular area of cleared land, mostly brown dirt, with some darker patches of soil. Several orange excavators and a yellow bulldozer are visible working on the site. A red truck is parked near the center. The site is surrounded by a blue chain-link fence with orange safety tape. To the north of the site is a large, two-story brick building with a flat roof, likely a school. To the east is a large, single-story white building with a flat roof. A multi-lane highway with several cars and trucks is visible in the background. The foreground shows residential houses and trees.

Fairview Elementary
Aerial View - Northwest
June 2017

An aerial photograph showing the construction site for Fairview Elementary. The site is a large, rectangular area of cleared land, mostly brown and sandy, with some concrete foundations visible. It is surrounded by various buildings, including a large blue and white industrial building to the northwest, a smaller brick building to the west, and a large white warehouse to the southeast. A parking lot with several cars is to the northeast. A road with traffic is visible at the top. A small pond is in the upper left. An excavator is working in the lower center of the site. The entire scene is captured from a high angle, showing the layout of the site and its surroundings.


Fairview Elementary
Aerial View - Northwest
July 2017

An aerial photograph showing the construction site for Fairview Elementary. The site is a large, cleared area of brown earth with some concrete foundations and rebar visible. Several excavators and trucks are working on the site. To the north of the construction site is a large, modern building with a blue and white facade. To the east is a parking lot filled with cars and a few small buildings. A multi-lane highway runs along the top of the image, with several buses and cars visible. The surrounding area includes trees and residential houses.


Fairview Elementary
Aerial View - Northwest
August 2017




Fairview Elementary
Aerial View - West
September 2017

An aerial photograph showing the construction of a new building at Fairview Elementary. The central focus is a large structure with its wooden frame exposed, featuring a grid of beams. To its right, a smaller, partially completed concrete building stands. A yellow crane is positioned near the wooden frame. The site is surrounded by various construction materials, including stacks of lumber and concrete blocks. In the background, there are existing school buildings, one with a blue facade and another with a red facade. The foreground and sides of the site are lined with trees, some showing autumn foliage in shades of red and orange. A parking lot filled with cars is visible on the right side of the construction area.


Fairview Elementary
Aerial View - Southwest
October 2017

An aerial photograph showing the construction of a new building at Fairview Elementary. The site is surrounded by existing school buildings, including a large blue-roofed structure on the left and a brick building below it. The new building's foundation and lower walls are visible, with some sections covered in orange safety fencing. A large pile of dirt and construction materials is in the foreground, with several excavators and trucks working on it. A parking lot with several cars is visible to the right. The scene is captured from a high angle, providing a clear view of the construction progress and the surrounding campus environment.


Fairview Elementary
Aerial View - Northwest
November 2017

An aerial photograph showing the construction of a new building at Fairview Elementary. The site is located between a large industrial building on the left and a multi-lane highway on the right. The new building is under construction, with its roof and some exterior walls visible. The roof is a mix of dark grey and orange-brown sections. The exterior walls are primarily light-colored, with some sections featuring blue and yellow panels. Construction equipment, including excavators and trucks, is visible on the site. A large pile of blue material is visible near the highway. The surrounding area includes a parking lot, some trees, and a residential house with a swimming pool in the bottom right corner.


Fairview Elementary
Aerial View - Northwest
December 2017

An aerial photograph showing the construction of Fairview Elementary school. The main building is a large, multi-winged structure with a dark roof and blue and orange exterior panels. A large section of the roof is covered with blue insulation. To the left, there is an existing brick building with a flat roof. The construction site is surrounded by parking lots filled with cars and trucks, and various construction materials and equipment are scattered around. In the background, a multi-lane highway runs horizontally across the top of the image. The foreground shows residential houses and trees.

Fairview Elementary
Aerial View - Northwest
January 2018

An aerial photograph of Fairview Elementary school during its construction phase in February 2018. The school building is a large, multi-winged structure with a complex roofline. The roof is primarily white, with several sections of blue insulation or temporary roofing visible. The exterior walls are a mix of brick and light-colored panels. The building is surrounded by a large parking lot filled with cars and trucks. To the left of the main building is a large, blue-roofed industrial or warehouse building. To the right is a smaller, tan-colored building. The surrounding area is covered in snow, indicating a winter setting. Various construction vehicles, including excavators, trucks, and cranes, are visible around the site. The overall scene depicts a busy construction project in a suburban or urban environment.

Fairview Elementary
Aerial View - Northwest
February 2018

An aerial photograph of Fairview Elementary school during a major renovation project in March 2018. The main building is a large, multi-winged structure with a flat roof. Significant portions of the exterior walls are covered in blue insulation or sheathing, while other sections show brickwork and wooden siding. The roof is cluttered with construction materials, including stacks of lumber, pipes, and various pieces of equipment like forklifts and cranes. To the left of the main building is a smaller, older brick structure. In the background, there's a large white industrial-style building with a blue roofline, a flagpole with the American flag, and a multi-lane highway with some traffic. The foreground shows a parking lot filled with cars, more construction materials, and a few trees. The overall scene depicts an active and complex construction site.

Fairview Elementary
Aerial View - Northwest
March 2018