



**Alder Water Testing June 2016**

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Diane Spangler 06/16/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
ALD01	Room 17a Staff Room Sink Faucet	6/16/16 03:21
ALD02	Drinking Fountain by Room 17B Left Side	6/16/16 03:26
ALD03	Drinking Fountain by Room 17B Right Side	6/16/16 03:27
ALD04	Room # 30 Drinking Fountain	6/16/16 03:33
ALD05	Room # 29 Drinking Fountain	6/16/16 03:35
ALD06	Room # 28 Drinking Fountain	6/16/16 03:37
ALD07	Room # 27 Drinking Fountain	6/16/16 03:39
ALD08	Room # 26 Drinking Fountain	6/16/16 03:41
ALD09	Room # 25 Drinking Fountain	6/16/16 03:43
ALD10	Room # 18 Drinking Fountain	6/16/16 03:47
ALD11	Room # 19 Drinking Fountain	6/16/16 03:48
ALD12	Drinking Fountain SW Hall Boys/Left/Tall	03:52
ALD13	<del>Drinking</del> Drinking Fountain Boys/Left/Tall Bottle Filler SW Hall	03:53
ALD14	Drinking Fountain Girls/Right/Short SW Hall	03:54
ALD15	Sink Faucet Room # 32	04:00

## Alder Water Testing June 2016

Sampled By: Laurence Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date
ALD16	Nurses office Sink	0323 6/16/16
ALD17	Rm 15 sink fountain	0324 "
ALD18	Rm 1 " " "	0337 "
ALD19	Rm 2	0339 "
ALD20	Trim fountain in hall	0345 "
ALD21	Rm 3 Sink fountain	0343 "
ALD22	Rm 4 " " "	0344 "
ALD23	Rm 5 " " "	0346 "
ALD24	Rm 4le " " "	0348 "
ALD25	Hall fountain between R. Rm 5.	0350 "
ALD26	Rm 8 " " "	0351 "
ALD27	Rm 9 " " "	0353 "
ALD28	Rm 10 " " "	0354 "
ALD29	Rm 11 " " "	0355 "
ALD30	Mrs. Menaco's Rm - Sink faucet	0358 "



Alder Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • Fax 503.667.6932

Sampled By: Lawrence Smith

Sample ID	Location (Classroom# or Faucet Loc.)	Date
ALD31	Rm 13 Sink Fountain	04/01
ALD32	Rm 14 " "	04/03
ALD33	Rm 21 " "	04/07
ALD34	Rm 22 " "	04/09
ALD35	Room 24 Drinking Fountain	04/10
ALD36	Room 23 Drinking Fountain	04/11
ALD37	Gym, hall between Cafe & Service - Tall	04/15
ALD38	" " - Short	04/17
ALD39	Kitchen Prep Sink Faucet Left	04/19
ALD40	Kitchen Prep Sink Faucet Right	04/20
ALD41	Kitchen Dishwash Sink East	04/21
ALD42		
ALD43		
ALD44		
ALD45		



Davis Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201st Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Diane Spangler 06/14/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
DAV01	Classroom #1 Drinking Fountain	6/14/16 22:12
DAV02	SE Hall Drinking Fountain by Restrooms Left/Tail	6/14/16 22:14
DAV03	SE Hall Drinking Fountain by Restrooms Right/Short	6/14/16 22:15
DAV04	Class Room #2 Drinking Fountain	6/14/16 22:19
DAV05	Room #3 Drinking Fountain	6/14/16 22:21
DAV06	Room #5 Drinking Fountain	6/14/16 22:24
DAV07	Room #4 Drinking Fountain	6/14/16 22:25
DAV08	Room #6 Drinking Fountain	6/14/16 22:29
DAV09	Room #7 Drinking Fountain	6/14/16 22:32
DAV10	Room #9 Drinking Fountain	6/14/16 22:34
DAV11	Room #8 Drinking Fountain	6/14/16 22:36
DAV12	Health room Sink faucet	6/14/16 22:39
DAV13	<del>Room #10</del> Gymn Hall Drinking Fountain by Boys Bathroom (Left Side)	6/14/16 22:51
DAV14	Gym Hall Drinking Fountain Girls bathroom (Right Side)	6/14/16 22:52
DAV15	<del>Room #11</del> Gym Hall Drinking Fountain by Ramp Left/Short	6/14/16 23:04
DAV 34	Gym west Hall Drinking Fountain by Ramp Right Side/Tail	6/14/16 23:05







Davis Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Lawrence Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date
DAV31	Rest Room East End Fountain	2058 6/14/16 ✓
DAV32	Rm. 23 Sink drinking fountain	2302 " ✓
DAV33	Rm 21 " " " "	2305 " ✓
<del>DAV34</del>	Rm 15 " " " "	↓ " ✓
DAV35	↗ ↘	2309 " ✓
DAV36	Rm 14 " " " "	2311 " ✓
DAV37		
DAV38		
DAV39		
DAV40		
DAV41		
DAV42		
DAV43		
DAV44		
DAV45		



Fairview Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • fax 503.667.6932

Sampled By: Diana Spanglin 06/15/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
FAV01	Library Drinking Fountain west wall Rm#12	6/15/16 02:39
FAV02	Drinking Fountain upstairs Hall by west stairway up	6/15/16 02:43
FAV03	Drinking Fountain upstairs Hall by west stairway up Bottle Filler	6/15/16 02:44
FAV04	Drinking Fountain Room #11	6/15/16 02:47
FAV05	Room #10 Drinking Fountain	6/15/16 02:50
FAV06	Room #9 Drinking Fountain	6/15/16 02:52
FAV07	Room #8 Drinking Fountain	6/15/16 02:56
FAV08	Room #7 Drinking Fountain	6/15/16 02:58
FAV09	Room #6 Drinking Fountain	6/15/16 03:01
FAV10	<del>Room #5</del> Upper Hall Drinking Fountain by East stairway Down	6/15/16 03:04
FAV11	Health Room sink	6/15/16 03:08
FAV12	Office File room Kitchenette Sink Faucet	6/15/16 03:09
FAV13	Room #11 Mailroom Drinking Fountain	6/15/16 03:11
FAV14	Room #10 Drinking Fountain	6/15/16 03:14
FAV15	Upper Hall East End by Restrooms Drinking Fountain Left side	6/15/16 03:16



Fairview Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Lawrence Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date
FAV16	Drinking fountain - Rm 21	0242 6/16/15
FAV17	Sink fountain - Rm 22A	0248 11'
FAV18	Hall drink fountains by Adulter Rm demonstration - Tall	0256 11'
FAV19	11' 11' - Short	0257 11'
FAV20	Kitchen dishwasher deep sink	0302 11'
FAV21	11' double deep sinks by repair	0303 11'
FAV22	Teacher lounge Sink	0305 11'
FAV23	11' Stream water machine	0306 11'
FAV24	Rm 21 Sink fountain	0309 11'
FAV25	Rm 25 11' (Shower water)	0312 11'
FAV26	Rm 24 11'	0316 11'
FAV27	Rm 23 11'	0319 11'
FAV28	Gym water fountain	0324 11'
FAV29		
FAV30		





Fairview Water Testing June 2016

Reynolds School District  
Administration Offices  
1204 NE 201<sup>st</sup> Avenue  
Fairview, OR 97024  
503.661.7200 • FAX 503.667.6932

Sampled By: Diana Spangler 06/15/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
FAV31	Upper Hall East End by Restrooms Right Side Drinking Fountain	6/15/16 03:17
FAV32	Room #15 Drinking Fountain	6/15/16 03:21
FAV33	Room #14 Drinking Fountain	6/15/16 03:26
FAV34	Room #13 Drinking Fountain	6/15/16 03:29
FAV35		
FAV36		
FAV37		
FAV38		
FAV39		
FAV40		
FAV41		
FAV42		
FAV43		
FAV44		
FAV45		



Glenfair Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Lawrence Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date
GLF01	Glenfair kitchen sink by door	6-13-2016 11:46
GLF02	Glenfair " sink by tray station	6-13-2016 11:48
GLF03	Glenfair cafe water fountain	6-13-2016 11:55
GLF04	Glenfair Rm 12 water fountain	6-14-2016 12:02
GLF05	Glenfair Rm 13 water fountain	6-14-2016 12:02
GLF06	Glenfair Hall west wall water fountain	6-14-2016 12:04
GLF07	Glenfair Rm 20 water fountain	6-14-2016 12:13
GLF08	Glenfair Rm 14 water fountain	6-14-2016 12:15
GLF09	Glenfair Rm 19 water fountain	6-14-2016 12:17
GLF10	Glenfair gym Drinking fountain	6-14-2016 12:28
GLF11	NOT USED	
GLF12		
GLF13		
GLF14		
GLF15		



Glenfair Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: \_\_\_\_\_

Sample ID	Location (Classroom# or Faucet Loc.)	Date
GLF16	East Hall left "Taller" Drinking Fountain	6/13/16 23:45
GLF17	East Hall left "Taller" Drinking Fountain Bottle Filler	6/13/16 23:53
GLF18	East Hall Right "Shorter" Drinking Fountain	6/13/16 23:54
GLF19	Staff Room Sink (wasn't posted)	6/14/16 00:00
GLF20	Staff Room kitchen water machine (wasn't posted)	6/14/16 00:04
GLF21	Main Office Health Room sink (wasn't posted)	6/14/16 00:09
GLF22	Room #2 Drinking Fountain	6/14/16 00:13
GLF23	Room #3 Drinking Fountain	6/14/16 00:16
GLF24	Room #4 Drinking Fountain	6/14/16 00:20
GLF25	Room #5 Drinking Fountain	6/14/16 00:23
GLF26	Room #6 Drinking Fountain	6/14/16 00:26
GLF27	Room 32133 Drinking Fountain South side	6/14/16 00:30
GLF28	Room 32133 Drinking Fountain North side	6/14/16 00:32
GLF29	Room #7 Drinking Fountain	6/14/16 00:41
GLF30	Room #8 Drinking Fountain	6/14/16 00:43



Glenfair Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Diane Spanglen 06/14/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
GLF31	Room #9 Drinking Fountain	6/14/16 00:45
GLF32	Room #10 Drinking Fountain	6/14/16 00:47
GLF33	END	
GLF34	Not Used	
GLF35		
GLF36		
GLF37		
GLF38		
GLF39		
GLF40		
GLF41		
GLF42		
GLF43		
GLF44		
GLF45		





Hartley Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Diane Spangler 06/15/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
HAR01	Health Room Sink Faucet	6/14/16 23:42
HAR02	South Hall East End Bathroom "8" Drinking Fountain left/short	6/14/16 23:46
HAR03	South Hall East End Bathroom "8" Drinking Fountain Right/Tall	6/14/16 23:47
HAR04	Room #1 Drinking fountain	6/14/16 23:50
HAR05	Room #3 Drinking fountain	6/14/16 23:53
HAR06	Room #2 Drinking Fountain	6/14/16 23:56
HAR07	Room #4 Drinking Fountain	6/14/16 23:58
HAR08	Room #5 Drinking Fountain	6/15/16 00:02
HAR09	Room #6 Drinking Fountain	6/15/16 00:04
HAR10	Room #8 Drinking Fountain	6/15/16 00:11
HAR11	Room #9 Drinking Fountain	6/15/16 00:16
HAR12	Room #11 Drinking Fountain	6/15/16 00:20
HAR13	Room #10 Drinking Fountain	6/15/16 00:26
HAR14	Room #13 Drinking Fountain	6/15/16 00:30
HAR15	Room #15 Drinking Fountain	6/15/16 00:33

## Hartley Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Laurence Spangler

Sample ID	Location (Classroom# or Faucet Loc.)		Date
HAR16	Cage Fountain - tall	near	2341 6/14/16
HAR17	" - short	"	2342 "
HAR18	Kitchen - deep sink sprayer		2344 "
HAR19	Dishwasher sink - sprayer		2346 "
HAR20	Rm. 21 Sink drinking fountain		2350 "
HAR21	Rm. 26 " "		2353 "
HAR22	Rm. 18 " "		2356 "
HAR23	Rm. 19 " "		2010 6/15/16
HAR24	Rm. 17 " "		2014 "
HAR25	Rm. 16 " "		2015 "
HAR26	Restroom drinking fountain - tall		2018 "
HAR27	" " - short		2020 "
HAR28	Rm. 14 Sink faucet		2023 "
HAR29	Gym drinking fountain - tall		2025 "
HAR30	" " - short		2026 "



Hartley Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Laurny Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date
HAR31	Teachers lounge - Sink - filtration = 0033	6/15/16
HAR32	11' - cooler - Brown system 0035	11'
HAR33	South Hall west end Bathroom "A" Drinking Fountain Tall Right	6/15/16 0041
HAR34	South Hall west end Bathroom "A" Drinking Fountain Short Left	6/15/16 0042
HAR35	Room #12 Sink Faucet	6/15/16 0043
HAR36	Portable "A" Drinking Fountain MFS Room	6/15/16 0100
HAR37		
HAR38		
HAR39		
HAR40		
HAR41		
HAR42		
HAR43		
HAR44		
HAR45		





Salish Ponds Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Diana Spangler 06/15/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
SAL01	Room # 9 Drinking Fountain	6/15/16 22:04 ✓
SAL02	Room # 11 Drinking Fountain	6/15/16 22:07 ✓
SAL03	Room # 10 Drinking Fountain	6/15/16 22:09 ✓
SAL04	Room # 12 Drinking Fountain	6/15/16 22:12 ✓
SAL05	Room # 13 Drinking Fountain	6/15/16 22:14 ✓
SAL06	Room # 15 Drinking Fountain	6/15/16 22:15 ✓
SAL07	Room # 14 Drinking Fountain	6/15/16 22:18 ✓
SAL08	Room # 6 Drinking Fountain	6/15/16 22:20 ✓
SAL09	Room # 7 Drinking Fountain	6/15/16 22:23 ✓
SAL10	Room # 5 Drinking Fountain	6/15/16 22:25 ✓
SAL11	Room # 4 Drinking Fountain	6/15/16 22:28 ✓
SAL12	Room # 2 Drinking Fountain	6/15/16 22:30 ✓
SAL13	Room # 3 Drinking Fountain	6/15/16 22:32 ✓
SAL14	Room # 1 Drinking Fountain	6/15/16 22:33 ✓
SAL15	Room: Kitchen Prep Sink South Wall West Side	6/15/16 22:40 ✓





Salish Ponds Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Diane Spangler 06/15/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
SAL31	Cafeteria Drinking Fountain Tall / Left	6/15/16 22:43 ✓
SAL32	Cafeteria Drinking Fountain Short / Right	6/15/16 22:46 ✓
SAL33	Kitchen wash sink faucet East End South wall Left Side	6/15/16 22:45 ✓
SAL34	Kitchen Sanitize sink faucet East End South wall Right Side	6/15/16 22:46 ✓
SAL35	Kitchen Dishwashing Sinks Faucet / Sprayer	6/15/16 22:48
SAL36		
SAL37		
SAL38		
SAL39		
SAL40		
SAL41		
SAL42		
SAL43		
SAL44		
SAL45		

Margaret Scott Water Testing June 2016

Sampled By: Diane Spangler 06/13/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
SCOTT01	Kitchen Dishwashing Sink	6/13/16 22:28
SCOTT02	Room 12 Drinking Fountain and Sink	6/13/16 22:34
SCOTT03	Room 14 Drinking Fountain and Sink	6/13/16 22:39
SCOTT04	Room 4 Drinking Fountain and Sink	6/13/16 22:46
SCOTT05	Room 2 Drinking Fountain and Sink	6/13/16 22:49
SCOTT06	Room 3 Drinking Fountain and Sink	6/13/16 22:53
SCOTT07	Room 4 Drinking Fountain and Sink	6/13/16 22:58
SCOTT08	Room 5 Drinking Fountain and Sink <small>wasnt posted</small>	6/13/16 23:02
SCOTT09	Counselor's Office and East End of library by Computer Lab. South Door.	6/13/16 23:07
SCOTT10	Gym Drinking Fountain left side shorter (west)	6/13/16 23:14
SCOTT11	Gym Drinking Fountain right side taller (East)	6/13/16 23:14
SCOTT12	END	
SCOTT13		
SCOTT14		
SCOTT15		

Entered At 6/14/16 @ 0908



Margaret Scott Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Lawrence Spangler

Sample ID	Location (Classroom# or Faucet Loc.)		Date
SCOTT16	M. Scott	Nurse Station / Office	6-13-2016
SCOTT17	M. Scott	Staff lounge	6-13-2016
SCOTT18	M. Scott	Kitchen soap sink	6-13-2016
SCOTT19	M. Scott	" North sink	6-13-2016
SCOTT20	M. Scott	cafe East water fountain	6-13-2016
SCOTT21	M. Scott	" " Battle fill station	6-13-2016
SCOTT22	M. Scott	" " West water fountain	6-13-2016
SCOTT23	M. Scott	lm 11 Drinking fountain	6-13-2016
SCOTT24	M. Scott	lm 13 " "	6-13-2016
SCOTT25	M. Scott	lm 10 " "	6-13-2016
SCOTT26	M. Scott	lm 9 " "	6-13-2016
SCOTT27	M. Scott	lm 8 " "	6-13-2016
SCOTT28	M. Scott	lm 6 " "	6-13-2016
SCOTT29	M. Scott	lm 7 " "	6-13-2016
SCOTT30	M. Scott	lm 19 portable DF	6-13-2016



Margaret Scott Water Testing June 2016

Reynolds School District  
Administration Offices  
1204 NE 201<sup>st</sup> Avenue  
Fairview, OR 97024  
503.661.7200 • FAX 503.667.6932

Sampled By: Laurence Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date
SCOTT31	M. Scott portable Dual Drinking Fountain	6-13-2016
SCOTT32		
SCOTT33		
SCOTT34		
SCOTT35		
SCOTT36		
SCOTT37		
SCOTT38		
SCOTT39		
SCOTT40		
SCOTT41		
SCOTT42		
SCOTT43		
SCOTT44		
SCOTT45		

## Sweetbriar Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Diane Spanglin 06/16/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
SWB01	Health room Bathroom sink Faucet	6/16/16 22:05
SWB02	Staff lounge in main office sink Faucet	6/16/16 22:08
SWB03	Girls Bathroom Drinking Fountain by main office	6/16/16 22:12
SWB04	Drinking fountain Gym Hall by main office Left Tall	6/16/16 22:15
SWB05	Drinking fountain Gym Hall by main office Left Bottle Filler	6/16/16 22:16
SWB06	Drinking Fountain Gym Hall by main office Right Short	6/16/16 22:17
SWB07	Room 22 Drinking Fountain	6/16/16 22:18
SWB08	Gym Drinking Fountain left/short	6/16/16 22:21
SWB09	Gym Drinking Fountain Right/Tall	6/16/16 22:22
SWB10	Kitchen prep sink Island Faucet	6/16/16 22:25
SWB11	Kitchen prep sink N. wall Left Faucet	6/16/16 22:26
SWB12	Kitchen prep sink N. wall Right Faucet/Sprayer	6/16/16 22:27
SWB13	Kitchen Dishwashing Sink Sprayer	6/16/16 22:28
SWB14	Room #19 Drinking Fountain	6/16/16 22:34
SWB15	Room #18 Left Drinking Fountain	6/16/16 22:37
SWB16	Room #18 Right Drinking Fountain	6/16/16 22:38







Troutdale Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Diane Spaulin 06/17/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
TDL01	105 stairs Hall Drinking fountain Access From Rm# 112	6/17/16 23:45
TDL02	North Storage Room off of Room 112 Drinking fountain	6/16/16 23:53
TDL03	Room # 107 <del>the</del> workroom sink	6/16/16 23:55
TDL04	Room # 115 Drinking Fountain	6/17/16 00:01
TDL05	Room # 117 Drinking fountain	6/17/16 00:03
TDL06	Room # 116 Drinking fountain	6/17/16 00:06
TDL07	Room # 119 Drinking fountain	6/17/16 00:09
TDL08	Room # 118 Drinking fountain	6/17/16 00:11
TDL09	Room # 121 Drinking fountain	6/17/16 00:14
TDL10	Room # 120 Drinking fountain	6/17/16 00:16
TDL11	Room # B-7 Drinking fountain	6/17/16 00:21
TDL12	Room # B-2 Drinking fountain	6/17/16 00:27
TDL13	Room # B-3 Drinking fountain	6/17/16 00:28
TDL14		
TDL15		

## Troutdale Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Lauren Sample

Sample ID	Location (Classroom# or Faucet Loc.)	Date
TDL16	Water fountain by office in hall - Tall	2345 6/16/16
TDL17	" " - Short	2348 "
TDL18	106 Sink fountain	2347 "
TDL19	Gym fountain - Tall	2350 "
TDL20	" " - Short	2353 "
TDL21	Portable - Ms. Butthold class - Sink fountain	0000 <del>6/17</del> 6/17
TDL22	Tall - Cafe fountain	0007 6/17
TDL23	Short - " " "	0008 6/17
TDL24	Kitchen - double deep sink faucet	0012 "
TDL25	" " - Dish washer tray sink	0013 "
TDL26	Teacher lounge - Sink	0017 "
TDL27	" " - ML100 dispenser	0018 "
TDL28	Rm B-5 - Sink fountain	0020 "
TDL29	" B-4 - " "	0022 "
TDL30	Breakroom hall by restrooms - fountain	0024 "



Troutdale Water Testing June 2016

Reynolds School District  
Administration Offices  
1204 NE 201<sup>st</sup> Avenue  
Fairview, OR 97024  
503.661.7200 • FAX 503.667.6932

Sampled By: Lauren Spade

Sample ID	Location (Classroom# or Faucet Loc.)	Date
TDL31	Rm B-10 Sink Fountain	6/17/16
TDL32		
TDL33		
TDL34		
TDL35		
TDL36		
TDL37		
TDL38		
TDL39		
TDL40		
TDL41		
TDL42		
TDL43		
TDL44		
TDL45		



Wilkes Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Laura M. Spina

Sample ID	Location (Classroom# or Faucet Loc.)		Date
WIL01	Wilkes Kitchen	North sink #1	3:32 am 6-14-2016
WIL02	Wilkes Kitchen	North sink #2	3:33 am 6-14-2016
WIL03	" Kitchen	Drinking Fountain Hall	3:33 am 6-14-2016
WIL04	" Kitchen	Drinking Fountain short	3:34 am 6-14-2016
WIL05	"	Rm 39 sink	3:36 am 6-14-2016
WIL06	"	Rm 36 sink/Drinking Fountain	3:38 am 6-14-2016
WIL07	Wilkes	Rm 35 sink	3:42 am 6-14-2016
WIL08	"	teacher Room sink	3:44 am 6-14-2016
WIL09	"	teacher room cooler	3:45 am 6-14-2016
WIL10	"	Rm #6 sink/Drinking Fountain	3:48 am 6-14-2016
WIL11	"	Rm #4 sink/Drinking Fountain	3:51 am 6-14-2016
WIL12	"	Rm #3 sink/Drinking Fountain	3:53 am 6-14-2016
WIL13	"	Rm #2 sink/Drinking Fountain	3:56 am 6-14-2016
WIL14	+	Rm #1 sink/Drinking Fountain	3:58 am 6-14-2016
WIL15	"	outside Rm #1 Hall Drinking Fountain	4:06 am 6-14-2016



Wilkes Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • Fax 503.667.6932

Sampled By: Diane Spangler 06/14/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
WIL16	East Hall Drinking Fountain Tall Left	6/14/16 03:32
WIL17	East Hall Drinking Fountain Short/Right	6/14/16 03:33
WIL18	<del>Room # 8</del> Room # 8 Sink	6/14/16 03:38
WIL19	Counselor's office Across From Rm 23 Dish Sink	6/14/16 03:47
WIL20	Room # 5 Sink with Drinking Fountain Attachment	6/14/16 03:50
WIL21	Gym Drinking Fountain Left, Short	6/14/16 03:57
WIL22	Gym Drinking Fountain Right Tall	6/14/16 03:58
WIL23	Sun Room / Old S. Locker Room	6/14/16 04:00
WIL24	Room # 29 Health Room	6/14/16 04:04
WIL25	Room # 7 Sink	06-14-16 04:09
WIL26	Room #10 Sink	06/14/16 04:13
WIL27	Drinking Fountain Hall Portable "C"	06/14/16 04:16
WIL28	Drinking Fountain D7 Portable	06/14/16 04:20
WIL29	Drinking Fountain D8 Portable (Sink attachment)	06/14/16 04:22
WIL30	END OF PAGE	



Wilkes Water Testing June 2016

Reynolds School District  
Administration Offices  
1204 NE 201<sup>st</sup> Avenue  
Fairview, OR 97024  
503.661.7200 • FAX 503.667.6932

Sampled By: Lawrence Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date
WIL31	Wilkes A portable North Drinking Fountain	6-14-2016
WIL32	" A portable South Drinking Fountain	6-14-2016
WIL33	" B portable North Drinking Fountain	6-14-2016
WIL34	B portable South Drinking Fountain	6-14-2016
WIL35		
WIL36		
WIL37		
WIL38		
WIL39		
WIL40		
WIL41		
WIL42		
WIL43		
WIL44		
WIL45		



Woodland Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • fax 503.667.6932

Sampled By: Diane Spangler 06/16/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
WDL01	Room 207 Drinking Fountain	6/15/16 23:14
WDL02	Upstairs Hall by elevator Left / Tall Drinking Fountain	6/15/16 23:18
WDL03	Upstairs Hall by elevator Right / Short Drinking Fountains	6/15/16 23:19
WDL04	Room 208 Drinking Fountain	6/15/16 23:24
WDL05	Room 209 Drinking Fountain	6/15/16 23:27
WDL06	Room 210 Drinking Fountain	6/15/16 23:32
WDL07	Room 211 Drinking Fountain	6/15/16 23:33
WDL08	Room 212 Drinking Fountain	6/15/16 23:36
WDL09	Room 213 Drinking Fountain	6/15/16 23:40
WDL10	Room 214 Drinking Fountain	6/15/16 23:43
WDL11	Room 215 Drinking Fountain	6/15/16 23:45
WDL12	Room 101 Drinking Fountain	6/15/16 23:54
WDL13	Room 102 Drinking Fountain	6/15/16 23:56
WDL14	Room 103 Drinking Fountain	6/15/16 23:58
WDL15	Room 104 Drinking Fountain	6/16/16 00:02

## Woodland Water Testing June 2016

Sampled By: Laurence Pender

Sample ID	Location (Classroom# or Faucet Loc.)	Date
WDL16	Cafe drinking fountain - Tall	6/15/16
WDL17	" " " - Short	" "
WDL18	Kitchen Preparation sink? Faucet	" "
WDL19	" " Double deep sink Faucet	" "
WDL20	Dish washer sink	" "
WDL21	Fry pot (Mudra) Rinse Sink	" "
WDL22	Sym fountain - Tall drinking	" "
WDL23	" " " - Short	" "
WDL24	Art's n' Crafts - Sink Fountain	" "
WDL25	Work Rm - office Sink Fountain	" "
WDL26	Break Room - Water cooler-city water	" "
WDL27	<del>Break</del> " " Sink	" "
WDL28	Down stairs Water fountain - Tall	" "
WDL29	" " " - Short	" "
WDL30	Rm 107 Sink Fountain	" "





Woodland Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Carver & Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date
WDL31	Rm 108 Sink Fountain	6/15/16
WDL32	Rm 109 " "	" "
WDL33	Rm 110 " "	" "
WDL34	Rm 111 " "	" "
WDL35	Rm 112 " "	" "
WDL36	Rm 113 " "	" "
WDL37	Rm 114 " "	" "
WDL38	Rm 115 " "	" "
WDL39	Rm 106 " "	" "
WDL40	Rm 105 " "	" "
WDL41		
WDL42		
WDL43		
WDL44		
WDL45		







# HB LEE WATER TESTING June 2016

Sample B1 Diana Samples 06/14/16

Sample ID	Room	Location	Notes	Time	Status
HB LEE 46	Rm 304	West wall	Central Sink	02:23	✓
HB LEE 47	Rm 304	West wall	Science Lab	02:24	✓
HB LEE 48	Rm 303	NE	Science Sink	02:37	✓
HB LEE 49	Rm 303	E	Central Science Sink	02:39	✓
HB LEE 50	Rm 303	SE	Science Sink	02:41	✓
HB LEE 51	Rm 303	NW	Science Sink	02:45	✓
HB LEE 52	Rm 303	W	Central Science Sink	02:46	✓
HB LEE 53	Rm 303	SW	Science Sink	02:48	✓
HB LEE 54					

LAST



Reynolds Middle Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • fax 503.667.6932

Sampled By: Diana Spangler 06/17/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
RMS01	Library Workroom sink Faucet (not Posted)	6/18/16 0233
RMS02	DF 300 Hall Left Tall	6/18/16 0237
RMS03	Bottle Filler 300 Hall Left Tall	6/18/16 0238
RMS04	DF Right Short 300 Hall	6/18/16 0239
RMS05	Room 401 Sink/Bubbler attachment	6/18/16 0244
RMS06	Room 802 Sink Faucet   Attachment	6/18/16 0247
RMS07	Room 803 Sink Faucet	6/18/16 0249
RMS08	Room 803 Sink Faucet	6/18/16 0250
RMS09	Room 803 Sink Faucet	6/18/16 0251
RMS10	400 Hall DF. Short left	6/18/16 0256
RMS11	800 Hall Bottle Filler Right	6/18/16 <del>0256</del> 0257
RMS12	400 Hall D.F. Tall Right	6/18/16 0258
RMS13	Room 804 Island   North	6/18/16 0300
RMS14	Room 804 East	6/18/16 0301
RMS15	Room 804 South	6/18/16 0302



Reynolds Middle Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Lauren Spangle

Sample ID	Location (Classroom# or Faucet Loc.)	Date
RMS16	Office mail Rm. Sink	0227 6/18/16
RMS17	Fountain across from Cofe in hall - Shark	0236 "
RMS18	" " " " - Tall	0237 "
RMS19	Staff lounge Sink	0238 "
RMS20	Far left deep sink - Kitchen	0242 " "
RMS21	Middle left " " - "	0243 "
RMS22	Right left " " - "	0244 "
RMS23	Pair of deep sinks on right -	0245 "
RMS24	Dishroom deep sink	0246 "
RMS25	Consession stand sink	0254 "
RMS26	Room 401 Sink	0301 "
RMS27	Hall Fountain - Shark	<del>0303</del> 0304 "
RMS28	" " - Shark	0304 "
RMS29	Room 405 Sink Fountain	0308 "
RMS30	Rm. 407 Fountain, Sink	0312 "



Reynolds Middle Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Laurence Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date
RMS31	419 Sink	6/18/16
RMS32	Rm 3 bus hall - Sink	6/18/16
RMS33	South Gym hall - drinking fountain - tall	"
RMS34	" " " " " " - Short	"
RMS35	Boys Locker Rm.	"
RMS36	Band Rm. sink fountain	"
RMS37	Hall by entrance - fanner	"
RMS38	Nursery at Annex - bar sink	"
RMS39	Changing table sink - nursery - west	"
RMS40	Nursery pantry sink	"
RMS41	" " " " " " dispenser	"
RMS42	Changing table - sink - East	"
RMS43	<del>Boys Locker</del> Pool area - South - fountain	"
RMS44	<del>Boys Locker</del> Stair Sink	"
RMS45		



Sampled By: Diane Spanglin 06/18/16 Reynolds Middle Water Testing June 2016

Sample ID	Location (Classroom# or Faucet Loc.)	Date
PMS 46	Rm 511 Island / East Faucet (Not Posted) science	6/18/16 03:28
PMS 47	Room 511 North East Faucet (Not Posted) science	6/18/16 03:09
PMS 48	Room 511 North West Faucet (Not Posted) science	6/18/16 03:10
PMS 49	Room 511 West wall North Faucet (Not Posted) science	6/18/16 03:11
PMS 50	Room 511 West wall South Faucet (Not Posted) science	6/18/16 03:12
PMS 51	Room 506 DF	6/18/16 03:18
PMS 52	500 Hall D.F. by Boys Restroom (west)	6/18/16 03:21
PMS 53	500 Hall Bottle Filler By Boys Restroom (west)	6/18/16 03:22
PMS 54	500 Hall DF by Girls Bathroom (East)	6/18/16 03:24
PMS 55	500 Hall Bottle Filler by Girls Bathroom East	6/18/16 03:25
PMS 56	Room 507 Sink Faucet Left Sink	6/18/16 03:28
PMS 57	Room 507 DF. on Right Sink	6/18/16 03:29
PMS 58	Room 508 Sink Faucet	6/18/16 03:34
PMS 59	6000 Hall outside North Balcony Doors Drinking Fountain	6/18/16 03:43
PMS 60	6000 Hall outside North Balcony Doors Bottle Filler	6/18/16 03:44
PMS 61	Girls Locker Room Drinking Fountain	6/18/16 03:53
PMS 62	N. Gym Boys Football Team Room	6/18/16 03:59

DF = Drinking Fountain



Walt Morey Middle Water Testing June 2016

Reynolds School District  
Administration Offices  
1204 NE 201<sup>st</sup> Avenue  
Fairview, OR 97024  
503.661.7200 • FAX 503.667.6932

Sampled By: Lawrence Springer

Sample ID	Location (Classroom# or Faucet Loc.)	Date
WMMMS01	1 <sup>st</sup> Floor hall drinking fountains - by Storage	0251 6/16/16
WMMMS02		
WMMMS03		
WMMMS04		
WMMMS05		
WMMMS06		
WMMMS07		
WMMMS08		
WMMMS09		
WMMMS10		
WMMMS11		
WMMMS12		
WMMMS13		
WMMMS14		
WMMMS15		



Walt Morey Middle Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Lawrence Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date
WMMMS16	Mrs. Pickett's Rm - Sink	0144 6/16/16
WMMMS17	Kitchen double sink	0146 "
WMMMS18	Scullery sink - Right side	0151 "
WMMMS19	" " - Left side	0153 "
WMMMS20	Dishwasher rinse Sink-disposal	0154 "
WMMMS21	Cape drinking fountain - tall	0156 "
WMMMS22	" " - Short	0159 "
WMMMS23	Gym fountain	0204 "
WMMMS24	Main office work room sink	0205 "
WMMMS25	Entrance courtyard tap water	0201 "
WMMMS26	Main hall- Rest Rm. fountain - left	0202 "
WMMMS27	" " " - Right	0203 "
WMMMS28	Sink fountain - Music room	0231 "
WMMMS29	Portable - drinking fountain by entrance - Tall	0234 "
WMMMS30	" " " - Short	0235 "



Walt Morey Middle Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • Fax 503.667.6932

Sampled By: Diane Spangler 06/16/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
WMMS31	Room 204 Science Sink Faucet <del>Room</del> West	6/16/16 01:54
WMMS32	Room 204 Science Sink Faucet South	6/16/16 01:55
WMMS33	Room 204 Science Sink Faucet East	6/16/16 01:56
WMMS34	Room 201A Science Sink Faucet	6/16/16 01:58
WMMS35	Room 203 Sink Faucet	6/16/16 02:00
WMMS36	Room 202 Sink Faucet	6/16/16 02:02
WMMS37	Room 201 Sink Faucet	6/16/16 02:03
WMMS38	Room 214 Sink Faucet	6/16/16 02:05
WMMS39	upstairs 200 Hall North Drinking Fountain by Storage (By Boys Restroom)	6/16/16 02:09
WMMS40	upstairs 200 Hall South Drinking Fountain by Storage (By Gls Restroom)	6/16/16 02:24
WMMS41	Room 221 Science Sink Faucet North	6/16/16 02:29
WMMS42	Room 221 Science Sink Faucet East	6/16/16 02:30
WMMS43	Room 221 Science Sink Faucet South	6/16/16 02:31
WMMS44	Room 222 Sink Faucet	6/16/16 02:34
WMMS45	Downstairs 100 Hall South Drinking Fountain by Room #122	6/16/16 02:46





# RHS Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • Fax 503.667.6932

Sampled By: Laurence Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date
RHS16	Drinking Fountain by entrance to C-15 Hall Left/Tall	6/17/16 22:35
RHS17	Bottle Filler by entrance to C-15 Hall Left	6/17/16 22:36
RHS18	Drinking Fountain by entrance to C-15 Hall Right/Short	6/17/16 22:37
RHS19	Drinking Fountain S. End E Hall Left/Tall	6/17/16 22:43
RHS20	Drinking Fountain S End E Hall Right/Short	6/17/16 22:44
RHS21	D.F. By C-13	6/17/16 22:45
RHS22	Sink Faucet Staff lounge By SMT	6/17/16 22:54
RHS23	Hot/cold water Machine in Staff Lounge By SMT	6/17/16 22:55
RHS24	DF By C-19	6/17/16 23:04
RHS25	D.F. West Hall by W-15 Left/Short	6/17/16 23:09
RHS26	D.F. West Hall by W-15 Right/Tall	6/17/16 23:10
RHS27	D.F. West entry by W-15 Left/Short	6/17/16 23:19
RHS28	D.F. West entry by W-15 Right/Tall	6/17/16 23:20
RHS29	N-1 Central Sink Faucet	6/17/16 23:42
RHS30	<del>N-1</del> N-1 North Sink Faucet	6/17/16 23:43

D.F. = Drinking Fountain

## RHS Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Laurence Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date
RHS31	N-2 corner sink	2344 6/17/16
RHS32	" " second from corner sink	2345 " "
RHS33	" " 3rd from corner sink	2346 " "
RHS34	" " closest to door sink	2347 " "
RHS35	N-3 " " "	2350 " "
RHS36	" " 2nd from door sink	2351 " "
RHS37	" " 3rd from door sink	2352 " "
RHS38	" " corner sink	2353 " "
RHS39	00c fountain by Nov. Hall, N10-14 door way	2351 " "
RHS40	P.4 Sink	<del>0000</del> 6/18/16
RHS41	P.3 " "	0001 6/18/16
RHS42	P.2 " "	0004 " "
RHS43	T-1 Sink Faucet (not posted)	0009 6/18/16
RHS44	Woodshop Hall Drinking Fountain ( <del>corner</del> ) by T-3	0011 6/18/16
RHS45	Drink. Fountain - short - near door to school	0019 " "
46	" " tall - " "	0026 " "
47	" " - short - <del>corner</del> from display case	0022 " "
48	" " - tall - " "	0023 " "

Reynolds High School Water Testing June 2016

Sampled By: Laurence Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date	
RHS 46	X	6/18/16	0018
RHS 47	X	6/18/16	0019
RHS 48	X	6/18/16	0020
RHS 49	D.F. Gym lobby by East Gym Left tall	6/18/16	0018
RHS 50	D.F. Gym lobby by East Gym Right/short	6/18/16	0019
RHS 51	D.F. Gym lobby by East Gym Right Bottle Filler	6/18/16	0020
RHS 52	DF Girls locker Room North Wall Left	6/18/16	0039
RHS 53	DF Girls locker Room North Wall Right	6/18/16	0040
RHS 54	DF Girls locker Room <sup>north</sup> Bottle Filler	6/18/16	0041
RHS 55	DF Girls locker Room Entry Hall	6/18/16	0042
RHS 56	PAC Concession Stand Sink (not posted)	6/18/16	0106
RHS 57	PAC Commons D.F. Right/Tall S. wall	6/18/16	0109
RHS 58	PAC Commons DF Left/Short S. wall	6/18/16	0114
RHS 59	PAC Choir Room Sink   D.F. Handle broken (same water line)	6/18/16	0120

D.F. = Drinking Fountain



Sampled By: Laurence Spivak Reynolds High School June 2012 Water Test

Sample ID	Location (Classroom# or Faucet Loc.)	Date
<del>RHS 62</del>	<del>Backstage Workshop D.F.</del>	<del>6/17/12</del>
<del>RHS 63</del>	<del>PAU Shop D.F.</del>	<del>"</del>
<del>RHS 64</del>	<del>metal shop D.F.</del>	<del>"</del>
RHS 62	Consession stand - sink	0030 6/18/12
RHS 63	Boys locker room - fountain	0037 " "
RHS 64	" " - fountain - tall	0040 " "
RHS 65	" " " - short	0041 " "
RHS 66	Band Rm sink - PAC	0129 " "
RHS 67	BACK Stage Workshop D.F.	0129 6/18/12
RHS 68	PAC UPSTAIRS COMMONS S. WALL D.F.	0133 6/18/12
RHS 69	DE <del>PAU</del> Silk screen Back Room of A-11	0144 6/18/12
RHS 70	PAU Shop D.F.	0156 6/18/12
RHS 71	metal shop D.F.	0159 6/18/12

D.F. = Drinking Fountain



RLA West Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Lauren C. Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date
RLAW01	Teachers lounge - sink faucet <del>over</del>	0119 6/15/16
RLAW02	" " - fountain on sink	0121 "
RLAW03	Nurses office - sink faucet	0123 "
RLAW04	Rm 14 - faucet + drink. Fountain (no water)	0125 "
RLAW05	Deep sink - Rm 14	0127 "
RLAW06	Reyer Rm. - Sink faucet + fountain (drain work)	0128 "
RLAW07	Rm. 13 - fountain (steps on)	<del>0134</del> 0133 "
RLAW08	Rm 12 - sink faucet	0136 "
RLAW09	Hall drinking fountain - tall + small - some	0139 "
RLAW10	Science Rm 23 - Sink to left on wall	0144 "
RLAW11	Food Service sink faucet	0147 "
RLAW12	Rm 11 fountain - (drinker - doesn't stop)	0212 "
RLAW13	Rm 10 " - (drinker)	0213 "
RLAW14		
RLAW15		



RLA West Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Diane Spangler 06/15/16

Sample ID	Location (Classroom# or Faucet Loc.)	Date
RLAW16	Room # 20 Drinking Fountain	6/15/16 01:22
RLAW17	Room # 21 Drinking Fountain	6/15/16 01:28
RLAW18	Upstairs Commons / Student store Sink Faucet	6/15/16 01:29
RLAW19	Room # 22 Science Sink East <del>middle</del> South Wall Faucet	6/15/16 01:32
RLAW20	Room # 22 Science Sink South Wall <del>West</del> Faucet	6/15/16 01:35
RLAW21	Room # 22 Science Sink South wall middle Faucet	6/15/16 01:37
RLAW22	Room # 22 Science Sink East Island Faucet	6/15/16 01:40
RLAW23	Upstairs West Hall Drinking Fountain Left/short	6/15/16 01:43
RLAW24	Upstairs West Hall Drinking Fountain Right/Tall	6/15/16 01:44
RLAW25	Room # 24 Drinking Fountain	6/15/16 01:50
RLAW26	Room # 25 Drinking Fountain	6/15/16 01:53
RLAW27	Room # 26 Drinking Fountain	6/15/16 01:55
RLAW28	Room # 27 Drinking Fountain	6/15/16 01:59
RLAW29	Room # 28 Drinking Fountain	6/15/16 02:03
RLAW30		



RLA East Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Lawrence Spangler

Sample ID	Location (Classroom# or Faucet Loc.)	Date
RLAE01	Building "A" Kitchen Sink Faucet	6/16/16 00:36 ✓
RLAE02	Building "A" SE Classroom Sink Faucet	6/16/16 00:38 ✓
RLAE03	Building "G" Kitchen Sink Faucet	6/16/16 00:47 ✓
RLAE04	Building "G" Drinking Fountain	6/16/16 00:49 ✓
RLAE05	Building "H" Kitchen Sink Faucet	6/16/16 00:55 ✓
RLAE06	Building "H" Drinking Fountain	6/16/16 00:56 ✓
RLAE07	Building "I" Drinking Fountain Left/ Tall	6/16/16 01:03 ✓
RLAE08	Building "I" Drinking Fountain Right/ Short	6/16/16 01:04 ✓
RLAE09	Building "I" Kitchen Sink Faucet	6/16/16 01:05 ✓
RLAE10	Building "I" Kitchen wash Station Sink Faucet	6/16/16 01:10 ✓
RLAE11	Building "J" Hall Drinking Fountain Left/ Tall	6/16/16 01:13 ✓
RLAE12	Building "J" Hall Drinking Fountain Right/ Short	6/16/16 01:14 ✓
RLAE13	Building "J" Room # 9 Sink Faucet	6/16/16 01:17 ✓
RLAE14	Building "J" Office Sink Faucet	6/16/16 01:20 ✓
RLAE15		



Four Corners Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: \_\_\_\_\_

Sample ID	Location (Classroom# or Faucet Loc.)	Date
4C's01	4-C water fountain by Café	6-14-2016
4C's02	4-C Dish wash station west wall	6-14-2016
4C's03	4-C Dish wash station North wall	6-14-2016
4C's04	4-C water fountain upstairs	6-14-2016
4C's05	4-C Track lounge	6-14-2016
4C's06		
4C's07		
4C's08		
4C's09		
4C's10		
4C's11		
4C's12		
4C's13		
4C's14		
4C's15		



## Administration Water Testing June 2016

Reynolds School District  
 Administration Offices  
 1204 NE 201<sup>st</sup> Avenue  
 Fairview, OR 97024  
 503.661.7200 • FAX 503.667.6932

Sampled By: Laurenne Spindel

Sample ID	Location (Classroom# or Faucet Loc.)	Date
ADMIN01	Ops Shop R.Rm. sink Facilities Warehouse	0517 6/18/16
ADMIN02	IT Conference Rm. sink IT Warehouse	0514 "
ADMIN03	Master Teacher - IT office IT Warehouse	0515 "
ADMIN04	Nutrition office cooler Nutrition WHS	0518 "
ADMIN05	Rest Room sink Nutrition WHS	0519 "
ADMIN06	Admin lounge water cooler	0529 "
ADMIN07	" " <del>Refr</del> Fridge	0531 "
ADMIN08	" " Sink	0532 "
ADMIN09	Build. A, Tuna lounge sink	0544 "
ADMIN10	1 <sup>st</sup> garage bay sink	0546 "
ADMIN11	Build. D, Ops office sink	0551 "
ADMIN12	Build. B, Rm Driver lounge - Sink	0555 "